

Invoice #5736

August 31, 2021
6:40:51 PMOrdered on
August 14, 2021

Workorder # 6954

| MAKE & MODEL | | FLEET NO. | PHONE | REP | CSH | PO # | TERMS | | |
|---------------------------------------|-------------------|-------------------|----------------|-------------|--------------|---------------|----------|-------|------|
| 2007 WESTERN STAR CONVENTIONAL 4900SA | | FLUID 9 | 1-877-443-5843 | | EDJ | LARRY20210814 | Net 1 | | |
| LICENSE NO. | KM IN/OUT | VIN | TORQUE | ENGINE SIZE | TRANSMISSION | COLOUR | PRD DATE | | |
| FLUID9 | 31349 HR / 117280 | 5KKPALCKX7PX55425 | | | | BLUE | | | |
| CATALOG | DESCRIPTION | | | QTY | PARTS | LABOR | DISC | TOTAL | Code |

| | | | | | | | | |
|-------------------|--|----|--------|--|--|--|--|------------|
| TT LM52811R24.516 | LM528 11R24.5 16 TIRE / ALL IN PRICE / | 12 | 375.00 | | | | | \$4,500.00 |
| FG VS545D | VALVE STEM W/O 90 | 12 | 3.95 | | | | | \$47.40 |
| GD 82-2166EA | 30 AMP ATO FUSE HOLDER 30A / #12 W/P | 1 | 3.90 | | | | | \$3.90 |
| GD 76-6218PK | 30 AMP ATO FUSE | 1 | .48 | | | | | \$0.48 |
| WS W01-377-8536 | AIR SPRING-AIR BAG | 1 | 148.73 | | | | | \$148.73 |
| SI 23532823SX | AIR COMPRESSOR | 1 | 637.64 | | | | | \$637.64 |
| WS A22-73379-005 | HVAC PANEL CONTROL | 1 | 595.06 | | | | | \$595.06 |
| WS 918Y998 | WS SIGNAL STAT | 1 | 81.38 | | | | | \$81.38 |
| WS RD-4180-84 | HVAC HEATER CABLE | 1 | 37.69 | | | | | \$37.69 |
| FG TBF72420 | ALCOHOL EVAPORATOR | 1 | 46.13 | | | | | \$46.13 |
| WS | SWITCH SPDT 2POS AMB/RED | 1 | 7.10 | | | | | \$7.10 |
| V4D17NTB00000000 | | | | | | | | |
| WS 620602 | AIRDRYER TURBO 2000 LH HEATED 12V | 1 | 526.34 | | | | | \$526.34 |
| PT OR284358X | D-2 GOVERNOR | 1 | 26.57 | | | | | \$26.57 |
| PT 236577N | GOVERNOR GASKET | 1 | 3.81 | | | | | \$3.81 |
| RF 20LBABC | 20LB ABC FIRE EXTINGUISHER | 1 | 180.00 | | | | | \$180.00 |
| FG AS1140 | SLACK ADJUSTER AUTO 1-1/2" 28 SP, 5.5 | 2 | 124.81 | | | | | \$249.62 |
| FG 19X1084 | CLEVIS PIN .50 X 1 7/8" | 2 | 2.31 | | | | | \$4.62 |
| PT 19X127 | CLEVIS PIN 1/4 X 1 1/4 | 2 | 1.01 | | | | | \$2.02 |
| GD AS3019 | 1/2 GUNITE CLEVIS | 2 | 15.50 | | | | | \$31.00 |
| FG E1781 | WASHER | 6 | 1.50 | | | | | \$9.00 |
| FG E1782 | THICK SHIM | 3 | .75 | | | | | \$2.25 |
| FB E-719 | WASHER | 2 | .91 | | | | | \$1.82 |
| TE BRE9208H | 1/2 X 29/32 GEAR CLAMP | 2 | 2.88 | | | | | \$5.76 |

Thank-you. We appreciate your business.

| | | | | |
|---------------------|----------|------------|--------------|--------------------|
| PAID BY | Parts | \$8,329.69 | Subtotal | \$12,589.69 |
| Account \$13,219.17 | Labour | \$4,260.00 | Non-Taxable | \$0.00 |
| | Freight | \$0.00 | GST | \$629.48 |
| | Other | \$0.00 | | |
| | Supplies | \$0.00 | TOTAL | \$13,219.17 |

WORK AUTHORIZATION AND

PAYMENT GUARANTEED BY: (PRINT NAME) _____ (SIGNATURE) _____ DATE: _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. I HEREBY GRANT YOU AND/OR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT JONES TRUCK & GEAR SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE FULL AMOUNT OF SERVICES THERETO. INTEREST ACCRUES ON ALL UNPAID ACCOUNTS FROM THE SPECIFIC RATE OF 2% PER MONTH (24% PER ANNUM) UNTIL ALL SUMS ARE PAID IN FULL. ALL COSTS OF COLLECTION OR ENFORCEMENT OF RIGHTS JONES TRUCK & GEAR SERVICE LTD. MAY HAVE, DIRECTLY OR INDIRECTLY ARISING HEREOF, INCLUSIVE OF ITS COSTS INCURRED ON A SOLICITOR AND HIS OWN CLIENT BASIS, SHALL BE ADDED TO THE TOTAL AMOUNT OWING AND SHALL BEAR INTEREST AS AFORESAID.

| MAKE & MODEL | | FLEET NO. | PHONE | REP | CSH | PO # | TERMS | | |
|---------------------------------------|-------------------|-------------------|----------------|-------------|--------------|---------------|----------|-------|------|
| 2007 WESTERN STAR CONVENTIONAL 4900SA | | FLUID 9 | 1-877-443-5843 | | EDJ | LARRY20210814 | Net 1 | | |
| LICENSE NO. | KM IN/OUT | VIN | TORQUE | ENGINE SIZE | TRANSMISSION | COLOUR | PRD DATE | | |
| FLUID9 | 31349 HR / 117280 | 5KKPALCKX7PX55425 | | | | BLUE | | | |
| CATALOG | DESCRIPTION | | | QTY | PARTS | LABOR | DISC | TOTAL | Code |

| | | | | | | | | | |
|--------------------|---|----|-------|--|--|--|--|----------|--|
| TE BRE9216H | 13/16 X 1-1/2 GEAR CLAMP | 2 | 2.98 | | | | | \$5.96 | |
| GD 2089-6-6 | 06MP X 06FP 90 ADAPTER | 2 | 4.64 | | | | | \$9.28 | |
| GD 9635S-18-L12-06 | METRIC ORB 18MM X 3/8 FEM NPT | 2 | 7.19 | | | | | \$14.38 | |
| GD 125-6C | 3/8 HOSE X 3/8 NPT FITTING BARB | 2 | 1.80 | | | | | \$3.60 | |
| PT 5526-038 | 3/8" ID HEATER HOSE | 5 | 3.53 | | | | | \$17.65 | |
| WS 08929302 | 60 SERIES OIL FILL TUBE GASKET | 1 | 3.86 | | | | | \$3.86 | |
| DP 12T35622-PTO | O-RING | 1 | 4.62 | | | | | \$4.62 | |
| DP 13T38286 | GASKET SHIFT CYL / END SHAFT COVER | 1 | 4.30 | | | | | \$4.30 | |
| DP 13T35597-PTO | GASKET - 82 SERIES "O" SHIFTER | 1 | 3.68 | | | | | \$3.68 | |
| GD PL-1362-4 | 1/4 TUBE UNION FITTING | 1 | 7.24 | | | | | \$7.24 | |
| GD PL-1374-4B | 1/4 TUBE X 1/4 NPT 45 ELBOW SWIVEL | 1 | 8.15 | | | | | \$8.15 | |
| GD PL-1315-4A | 1/4 TUBE X 1/8 NPT 90 ELBOW | 1 | 6.15 | | | | | \$6.15 | |
| GD 2040-8-8 | 08MP-08FP ADAPTER EXPANDER | 1 | 13.84 | | | | | \$13.84 | |
| GD 2021-8-10 | #10 JIC X 1/2"NPT ADAPTER STR | 1 | 2.91 | | | | | \$2.91 | |
| FG 89 | BULB | 5 | 1.09 | | | | | \$5.45 | |
| GD 46783EA | AMBER DIECAST MARKER LAMP | 1 | 7.64 | | | | | \$7.64 | |
| PT SB4411 | 4411 SEALED BEAM LAMP FOR 64931EA | 3 | 6.42 | | | | | \$19.26 | |
| WS 1035A | 2" LED AMBER MARKER LAMP | 3 | 13.99 | | | | | \$41.97 | |
| PT 5-025 | 3/8" SPLIT LOOM | 3 | .25 | | | | | \$0.75 | |
| PT 761240 | SHRINK CRIMP BUTT CONNECTORS YELLOW | 5 | .91 | | | | | \$4.55 | |
| PT 761245 | SHRINK CRIMP BUTT CONNECTORS BLUE | 10 | .62 | | | | | \$6.20 | |
| PT 761244 | SHIRNK CRIMP BUTT CONNECTORS RED | 2 | .60 | | | | | \$1.20 | |
| PT 761650 | 1/4 RING CRIMP / SHRINK BLUE | 2 | .72 | | | | | \$1.44 | |
| FT AF25247 | AIR FILTER | 2 | 81.60 | | | | | \$163.20 | |
| NL BUGWINDOW | BUG WINDSHIELD WASHER FLUID PER/LITER | 1 | .99 | | | | | \$0.99 | |
| NL 9100RU4947 | HD EXT. LIFE 50/50 ANTIFREEZE (PER / L) | 52 | 3.24 | | | | | \$168.48 | |
| NL 5404B14981 | SYNTHETIC HI/LO GREASE (PER TUBE) | 3 | 6.76 | | | | | \$20.28 | |
| NL 75509B4958 | KFL SAFE-T-BRAKE ANTIFREEZE .950 L | 1 | 4.79 | | | | | \$4.79 | |
| WS RD-3-8416-0 | WESTERN STAR CABIN AIR FILTER | 1 | 50.13 | | | | | \$50.13 | |
| FT FS1029W | WATER SEPERATOR FUEL FILTER | 1 | 15.96 | | | | | \$15.96 | |
| EHC50F | EHC (\$.50/FILTER) | 1 | .50 | | | | | \$0.50 | |
| FT LF3620 | OIL FILTER | 1 | 20.03 | | | | | \$20.03 | |
| EHC100F | EHC (\$1.00/FILTER) | 1 | 1.00 | | | | | \$1.00 | |
| NL 3182CS4944 | 50W SYN. TRANS FLUID | 4 | 9.99 | | | | | \$39.96 | |
| EHC10 | EHC (\$.10/LITER) | 4 | .10 | | | | | \$0.40 | |

Thank-you. We appreciate your business.

| | | | | |
|--------------------------------|----------|------------|--------------|--------------------|
| PAID BY Account \$13,219.17 | Parts | \$8,329.69 | Subtotal | \$12,589.69 |
| | Labour | \$4,260.00 | Non-Taxable | \$0.00 |
| | Freight | \$0.00 | GST | \$629.48 |
| | Other | \$0.00 | | |
| | Supplies | \$0.00 | TOTAL | \$13,219.17 |

WORK AUTHORIZATION AND

PAYMENT GUARANTEED BY: (PRINT NAME) _____ (SIGNATURE) _____ DATE: _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. I HEREBY GRANT YOU AND/OR EMPLOYEES PERMSSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT JONES TRUCK & GEAR SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE FULL AMOUNT OF SERVICES THERETO. INTEREST ACCRUES ON ALL UNPAID ACCOUNTS FROM THE SPECIFIC RATE OF 2% PER MONTH (24% PER ANNUM) UNTIL ALL SUMS ARE PAID IN FULL. ALL COSTS OF COLLECTION OR ENFORCEMENT OF RIGHTS JONES TRUCK & GEAR SERVICE LTD. MAY HAVE, DIRECTLY OR INDIRECTLY ARISING HEREOF, INCLUSIVE OF ITS COSTS INCURRED ON A SOLICITOR AND HIS OWN CLIENT BASIS, SHALL BE ADDED TO THE TOTAL AMOUNT OWING AND SHALL BEAR INTEREST AS AFORESAID.


| MAKE & MODEL | | FLEET NO. | PHONE | REP | CSH | PO # | TERMS | | |
|---------------------------------------|-------------------|-------------------|----------------|-------------|--------------|---------------|----------|-------|------|
| 2007 WESTERN STAR CONVENTIONAL 4900SA | | FLUID 9 | 1-877-443-5843 | | EDJ | LARRY20210814 | Net 1 | | |
| LICENSE NO. | KM IN/OUT | VIN | TORQUE | ENGINE SIZE | TRANSMISSION | COLOUR | PRD DATE | | |
| FLUID9 | 31349 HR / 117280 | 5KKPALCKX7PX55425 | | | | BLUE | | | |
| CATALOG | DESCRIPTION | | | QTY | PARTS | LABOR | DISC | TOTAL | Code |

| | | | | |
|----------------|--------------------------------|----|------|----------|
| NL 21781B14944 | 0W/40 SYN. ADV HD CK4 ENG. OIL | 37 | 7.51 | \$277.87 |
| EHC10 | EHC (\$.10/LITER) | 37 | .10 | \$3.70 |

| | | | | |
|----------------|-------------------------------------|---|-------|----------|
| JT TIRE REPAIR | FLAT TIRE REPAIR INNER PLUG / PATCH | 4 | 55.00 | \$220.00 |
|----------------|-------------------------------------|---|-------|----------|

| | | | | |
|----------|---------------------|--|--|----------|
| CVIP-TRI | CVIP - TRIDEM TRUCK | | | \$300.00 |
|----------|---------------------|--|--|----------|

| | | | | |
|----|----------------------------|----|--------|------------|
| SL | SHOP LABOR (PER HOUR RATE) | 36 | 110.00 | \$3,960.00 |
|----|----------------------------|----|--------|------------|



Thank-you. We appreciate your business.

| | | | | |
|---------------------|----------|------------|--------------|--------------------|
| PAID BY | Parts | \$8,329.69 | Subtotal | \$12,589.69 |
| Account \$13,219.17 | Labour | \$4,260.00 | Non-Taxable | \$0.00 |
| | Freight | \$0.00 | GST | \$629.48 |
| | Other | \$0.00 | | |
| | Supplies | \$0.00 | TOTAL | \$13,219.17 |

WORK AUTHORIZATION AND

PAYMENT GUARANTEED BY: (PRINT NAME) _____ (SIGNATURE) _____ DATE: _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. I HEREBY GRANT YOU AND/OR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT JONES TRUCK & GEAR SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE FULL AMOUNT OF SERVICES THERETO. INTEREST ACCRUES ON ALL UNPAID ACCOUNTS FROM THE SPECIFIC RATE OF 2% PER MONTH (24% PER ANNUM) UNTIL ALL SUMS ARE PAID IN FULL. ALL COSTS OF COLLECTION OR ENFORCEMENT OF RIGHTS JONES TRUCK & GEAR SERVICE LTD. MAY HAVE, DIRECTLY OR INDIRECTLY ARISING HEREOF, INCLUSIVE OF ITS COSTS INCURRED ON A SOLICITOR AND HIS OWN CLIENT BASIS, SHALL BE ADDED TO THE TOTAL AMOUNT OWING AND SHALL BEAR INTEREST AS AFORESAID.

| MAKE & MODEL | | FLEET NO. | PHONE | REP | CSH | PO # | TERMS | | |
|---------------------------------------|-------------------|-------------------|----------------|-------------|--------------|---------------|----------|-------|------|
| 2007 WESTERN STAR CONVENTIONAL 4900SA | | FLUID 9 | 1-877-443-5843 | | EDJ | LARRY20210814 | Net 1 | | |
| LICENSE NO. | KM IN/OUT | VIN | TORQUE | ENGINE SIZE | TRANSMISSION | COLOUR | PRD DATE | | |
| FLUID9 | 31349 HR / 117280 | 5KKPALCKX7PX55425 | | | | BLUE | | | |
| CATALOG | DESCRIPTION | | | QTY | PARTS | LABOR | DISC | TOTAL | Code |

NOTES:

- CVIP TRUCK.
- CATEGORY A INSPECTION PERFORMED: ALL WHEELS AND DRUMS REMOVED. ALL DRUMS AND SHOES INSPECTED AND DATA RECORDED FOR CVIP.
- TORQUE ALL WHEEL LUG NUTS TO 500 FT/LBS.
- FILL ALL TIRE PRESSURES TO REQUIRED SPEC.
- ALL BRAKES ADJUSTED TO SPEC.
- LIFT UNIT AND SUPPORT ON JACK STANDS FOR CVIP INSPECTION.
- R&R ALL FRT STEER WHEELS FOR INSPECTION. 1ALS / 1ARS.
- R&R ALL REAR DRIVE AXLE S WHEELS FOR INSPECTION. 2ALS / 2ARS / 3ALS / 3ARS / 4ALS / 4ARS.
- R&R TWELVE DRIVE WHEELS AND INSTALL WITH TWELVE NEW DRIVE TIRES.
- ALL IN PRICE INCLUDES ONE NEW TIRE WITH TAX LEVY, MOUNTING / REMOUNTING, BALANCING BEADS, TIRE PRESSURES AS REQUIRED BY THE MANUFACTURER, R&R WHEELS AND TORQUE WHEEL NUTS TO 500 FT/LBS. NEW VALVE STEMS AND GST NOT INCLUDED.

-
- CUSTOMER IS RESPONSIBLE FOR THE RETORQUE OF REQUIRED WHEEL NUTS BETWEEN THE NEXT 50 TO 100 KMS OF SERVICE.
 - RETORQUE 1ALS / 1ARS / 2ALS / 2ARS / 3ALS / 3ARS / 4ALS / 4ARS WHEEL NUTS TO 500 FT/LBS.
 - JONES TRUCK PROVIDES A COURTESY RETORQUE FOR ALL WHEEL NUTS REMOVED AT TIME OF REPAIR.
-

- DIAGNOSE / REPAIR AIR LEAK ON DRIVER SIDE LOCATED BEHIND SLEEPER.
- DIAGNOSE / REPAIR AIR LEAK LOCATED ON TOP OF FIREWALL COMING FROM SOLENOID.
- DIAGNOSE / REPAIR RODA DEACO VALVE.
- DIAGNOSE / REPAIR READING LAMP ON DRIVER SIDE / MIDDLE LOCATED INSIDE CAB.
- REPAIR 5 FLAT TIRES ON DRIVE AXLES.
- ADJUST CLUTCH TO REQUIRED SPEC.
- R&R FOUR BATTERIES AND REPLACE WITH FOUR NEW BATTERIES. CUSTOMER HAD TWO NEW BATTERIES THAT WERE DISCHARGED THAT JONES TRUCK WILL CHARGE AND GIVE BACK TO THE CUSTOMER. TWO CORES WILL BE CHARGED TO THE CUSTOMER.
- R&R AIR COMPRESSOR AND REPLACE WITH NEW.
- R&R AIR DRYER AND REPLACE WITH NEW.
- R&R GOVERNOR AND REPLACE WITH NEW.
- R&R ALCOHOL SNIFFER FOR AIR SYSTEM AND REPLACE WITH NEW.
- R&R MAIN COOLANT HOSE GOING TO AIR COMPRESSOR AND REPLACE WITH NEW.
- R&R HVAC CONTROL MODULE AND REPLACE WITH NEW.
- R&R SIGNAL STAT AND REPLACE WITH NEW.
- DIAGNOSE / REPAIR MIRROR LAMP NOT WORKING WITH SWITCH.
- DIAGNOSE / REPAIR DRIVER SIDE WORK LAMP LOCATED ON SLEEPER.
- DIAGNOSE / REPAIR PASSENGER SIDE HIGH BEAM HEADLIGHT SHORTING ISSUE.
- DIAGNOSE / REPAIR PASSENGER SIDE FOGLAMP.

Thank-you. We appreciate your business.

| | | | | |
|---------------------|----------|------------|--------------|--------------------|
| PAID BY | Parts | \$8,329.69 | Subtotal | \$12,589.69 |
| Account \$13,219.17 | Labour | \$4,260.00 | Non-Taxable | \$0.00 |
| | Freight | \$0.00 | GST | \$629.48 |
| | Other | \$0.00 | | |
| | Supplies | \$0.00 | TOTAL | \$13,219.17 |


WORK AUTHORIZATION AND

PAYMENT GUARANTEED BY: (PRINT NAME) _____ (SIGNATURE) _____ DATE: _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. I HEREBY GRANT YOU AND/OR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT JONES TRUCK & GEAR SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATSOEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE FULL AMOUNT OF SERVICES THERETO. INTEREST ACCRUES ON ALL UNPAID ACCOUNTS FROM THE SPECIFIC RATE OF 2% PER MONTH (24% PER ANNUM) UNTIL ALL SUMS ARE PAID IN FULL. ALL COSTS OF COLLECTION OR ENFORCEMENT OF RIGHTS JONES TRUCK & GEAR SERVICE LTD. MAY HAVE, DIRECTLY OR INDIRECTLY ARISING HEREOF, INCLUSIVE OF ITS COSTS INCURRED ON A SOLICITOR AND HIS OWN CLIENT BASIS, SHALL BE ADDED TO THE TOTAL AMOUNT OWING AND SHALL BEAR INTEREST AS AFORESAID.

| MAKE & MODEL | | FLEET NO. | PHONE | REP | CSH | PO # | TERMS | | |
|---------------------------------------|-------------------|-------------------|----------------|-------------|--------------|---------------|----------|-------|------|
| 2007 WESTERN STAR CONVENTIONAL 4900SA | | FLUID 9 | 1-877-443-5843 | | EDJ | LARRY20210814 | Net 1 | | |
| LICENSE NO. | KM IN/OUT | VIN | TORQUE | ENGINE SIZE | TRANSMISSION | COLOUR | PRD DATE | | |
| FLUID9 | 31349 HR / 117280 | 5KKPALCKX7PX55425 | | | | BLUE | | | |
| CATALOG | DESCRIPTION | | | QTY | PARTS | LABOR | DISC | TOTAL | Code |

- DIAGNOSE / REPAIR BEACON LAMPS NOT FUNCTIONING.
- DIAGNOSE / REPAIR PASSENGER SIDE FENDER MARKER LIGHT NOT WORKING.
- DIAGNOSE / REPAIR PASSENGER SIDE 2" MARKER LAMP.
- DIAGNOSE / REPAIR PASSENGER SIDE MARKER LAMP LOCATED ON TOP OF TANK.
- DIAGNOSE / REPAIR 2 OUTSIDE 3 IN THE TREE MARKER LIGHTS LOCATED ON TOP REAR OF TANK.
- DIAGNOSE / REPAIR LICENSE PLATE LAMP.
- DIAGNOSE / REPAIR 4 WORK LIGHTS LOCATED ON TOP OF TANK.
- REPAIR BROKEN AIRLINE UNDER DRIVERS SIDE TANK CONTROLLERS. INSTALL UNION.
- R&R OIL FILL TUBE GASKET WITH NEW.
- R&R 2ARS AIRBAG AND REPLACE WITH NEW.
- REPLACE FIRE EXTINGUISHER WITH NEW.
- UNSEIZE BRAKE CLEVIS PINS USING AIR HAMMER AND PENETRATING OIL.
- INSTALL DRIVERS SIDE STEP BOLTS WITH NEW.
- GREASE COMPLETE TRUCK FRONT TO REAR ONCE.
- R&R TRANSMISSION OIL AND REINSTALL AFTER REPAIRS TO PTO WERE MADE. R&R SHIFT COVER TO REPLACE GASKET WITH NEW.
- R&R 1ALS / 3ALS SLACK ADJUSTERS AND REPLACE WITH NEW.
- R&R ENGINE OIL / ENGINE LUBE FILTER AND REPLACE WITH NEW.
- R&R TWO FUEL FILTERS AND REPLACE WITH NEW.
- ALL FLUID FILTERS FILLED BEFORE INSTALLATION AS REQUIRED BY THE OEM MANUFACTURER.
- GREASE COMPLETE TRUCK FRT TO REAR TWICE.
- R&R TWO ENGINE AIR FILTER AND REPLACE WITH NEW
- R&R CABIN FILTER AND REPLACE WITH NEW



Thank-you. We appreciate your business.

| | | | | |
|--------------------------------|----------|------------|--------------|--------------------|
| PAID BY Account \$13,219.17 | Parts | \$8,329.69 | Subtotal | \$12,589.69 |
| | Labour | \$4,260.00 | Non-Taxable | \$0.00 |
| | Freight | \$0.00 | GST | \$629.48 |
| | Other | \$0.00 | | |
| | Supplies | \$0.00 | TOTAL | \$13,219.17 |

WORK AUTHORIZATION AND

PAYMENT GUARANTEED BY: (PRINT NAME) _____ (SIGNATURE) _____ DATE: _____

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. I HEREBY GRANT YOU AND/OR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT JONES TRUCK & GEAR SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL. AN EXPRESS MECHANICS LIEN IS HEREBY ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE FULL AMOUNT OF SERVICES THERETO. INTEREST ACCRUES ON ALL UNPAID ACCOUNTS FROM THE SPECIFIC RATE OF 2% PER MONTH (24% PER ANNUM) UNTIL ALL SUMS ARE PAID IN FULL. ALL COSTS OF COLLECTION OR ENFORCEMENT OF RIGHTS JONES TRUCK & GEAR SERVICE LTD. MAY HAVE, DIRECTLY OR INDIRECTLY ARISING HEREOF, INCLUSIVE OF ITS COSTS INCURRED ON A SOLICITOR AND HIS OWN CLIENT BASIS, SHALL BE ADDED TO THE TOTAL AMOUNT OWING AND SHALL BEAR INTEREST AS AFORESAID.